

## **ITEM 22. MILL HILL RISK ASSESSMENT**

The attached Mill Hill Risk assessment was written by Colin Hardy in November 2021.

I walked the Mill Hill footpath this week to assess whether there has been any significant change in **hazard/risk** since November and make the following observations:

There is very poor visibility where the footpath from Mill Hill meets School Road. The hedge on the right of the footpath is now quite overgrown and there is little visibility to the right and because of the property wall, zero visibility to the left. It is therefore not clear to those unfamiliar with the area that they will step out straight onto the road.

**Parish Council to consider whether a sign warning of traffic may be appropriate.**

There are a number of branches and brambles encroaching the path. I have asked Andrew to cut these back when he next is on footpath strimming duty.

Jane Soanes